

State of Utah

Department of Natural Resources

MICHAEL R. STYLER Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA
Division Director

Lieutenant Governor

Representatives Present During the Inspection:

Company Mike Davis

Pete Hess Environmental Scientist III

Inspection Report

Permit Number:	C0410002
Inspection Type:	PARTIAL
Inspection Date:	Monday, August 11, 2008
Start Date/Time:	8/11/2008 11:10:00 AM
End Date/Time:	8/11/2008 1:25:00 PM
Last Inspection:	Wednesday, July 23, 2008

Inspector: Pete Hess, Environmental Scientist III

Weather: <u>Sunny, warm; 80's F.</u> InspectionID Report Number: <u>1728</u>

> Accepted by: jhelfric 8/18/2008

Permitee: CANYON FUEL COMPANY LLC
Operator: CANYON FUEL COMPANY LLC

Site: SUFCO MINE

Address: 397 S 800 W, SALINA UT 84654

County: SEVIER

JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

Mineral	Ownership
---------	-----------

Types of Operations

26,766.95	Total Permitted	✓ Federal	✓ Underground
27.36	Total Disturbed	✓ State	Surface
	Phase I	☐ County	Loadout
	Phase II	☐ Fee	Processing
	Phase III	☐ Other	Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The Permittee notified the Division on August 8, 2008, that the second quarter of 2008 surface and ground water monitoring information for the SUFCO Mine permit area had been successfully loaded into the electronic data base pipeline. The Permittee continues to meet this Special Condition included in Attachment "A" of the current State permit.

Inspector's Signature:

Pete Hess, Environmental Scientist III
Inspector ID Number: 46

Date

Tuesday, August 12, 2008

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0410002 Inspection Type: PARTIAL

Inspection Date: Monday, August 11, 2008

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcemen
1.	Permits, Change, Transfer, Renewal, Sale	\checkmark		\checkmark	
2.	Signs and Markers	V			
3.	Topsoil	✓			
4.a	Hydrologic Balance: Diversions	✓			
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓		✓	
4.c	Hydrologic Balance: Other Sediment Control Measures	✓			
4.d	Hydrologic Balance: Water Monitoring	✓		✓	
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments	V		✓	
8.	Noncoal Waste	✓			
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.a	Roads: Construction, Maintenance, Surfacing	V		✓	
16.b	Roads: Drainage Controls	✓			
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations	✓			
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance	✓		✓	
22.	Other				

Permit Number: C0410002 Inspection Type: PARTIAL

Inspection Date: Monday, August 11, 2008

Page 3 of 3

1. Permits, Change, Transfer, Renewal, Sale

The Permittee is evaluating the installation of a secondary impoundment located below the Mine site sediment pond just above the spring collection field. The processing of the coal waste material at the roadside site is also being evaluated by the Permittee. A new design for a tipple sump is being prepared for submittal. The new sump will allow a 992 front end loader bucket to dip water and disperse it on the tipple area operational areas for dust suppression purposes.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

The Permittee has recently completed the cleanout of the Mine site sediment pond. The material removed was hauled to the waste rock site, where I it is being allowed to dry.

4.d Hydrologic Balance: Water Monitoring

The Mine has received rainfall over the past several weeks, due to monsoonal effect of two hurricanes which came ashore in Texas. Mr. Davis indicated that 0.84 inches have been received in August; June and July were both dry months.

7. Coal Mine Waste, Refuse Piles, Impoundments

The Permittee constructed a drying area for the sediment pond muck at the toe of the waste rock outslope, with a ditch connecting the area to the waste rock pond. The slurry material is drying primarily by evaporation.

16.a Roads: Construction, Maintenance, Surfacing

To date, construction of the Quitchupah road connecting the Mine with Route 10 has not been initiated. Mr. Davis indicated that all permits are in place for the construction.

21. Bonding and Insurance

The Permittee has recently renewed the general liability insurance coverage for the Mine, effective August 1, 2008. Coverage amounts for gneral liability and each occurrence categories are adequate; coverage for explosive usage is provided. The cancellation clause has been properly modified to make notification to the Division should cancellation of the policy or other issue affecting the policy occur.